

## ORDINANCE 99-31-CM

WHEREAS, PURSUANT TO CURRENT INDIANA CODE Sections 8-17-1-40,9-211-2 and 9-21-1-3, it has been determined by the Board of Commissioners of Tippecanoe County, upon the basis of an Engineering and Traffic Investigation, that the regulatory signs, as listed below, are reasonable and safe and are in conformance with Indiana Manual on Uniform Traffic Control Devices.

NOW, THEREFORE, BE IT ORDAINED by the Board of Commissioners of Tippecanoe County Indiana that regulatory signs at the following intersections shall be established as follows:

- 1.) A 30" High Intensity Stop sign installed on Lucinda Lane at Shafer Drive in Shafers Acres Subdivision.
- 2.) 30" High Intensity Stop signs installed on Bowfield Way at Hunter Road in Pine View Farms Subdivision, Phase II, Section 2.
- 3.) A 36" High Intensity Yield sign installed on Temple Court East at Hunter Road in Pine View Farms Subdivision, Phase II, Section 2.
- 4.) A 36" High Intensity Yield sign installed on Temple Court West at Hunter Road in Pine View Farms Subdivision, Phase II, Section 2.
- 5.) A 36" High Intensity Yield sign installed on Depauw Drive at Hunter Road in Pine View Farms Subdivision, Phase II, Section 1.
- 6.) A 36" High Intensity Yield sign installed on Depauw Court at Hunter Road in Pine View Farms Subdivision, Phase II, Section 1.
- 7.) A 30" High Intensity Stop sign installed on West Indianbrook Drive at County Road 300 South in Indianbrook Subdivision.
- 8.) A 30" High Intensity Stop sign installed on East Indianbrook Drive at County Road 300 South in Indianbrook Subdivision.
- 9.) A 36" High Intensity Stop sign installed on Cameron Lane at County Road 550 East in Highland Meadows Subdivision.
- 10.) A 36" High Intensity Stop sign installed on Sterling Drive at County Road 50 North in Highland Meadows Subdivision.
- 11.) A 36" High Intensity Yield sign installed on Stuart Court at Sterling Drive in Highland Meadows Subdivision.
- 12.) A 36" High Intensity Yield sign installed on Sterling Drive at Cameron Lane in Highland Meadows Subdivision.
- 13.) A 30" High Intensity Stop sign placed on Edinburgh Court at Sterling Drive in Highland Meadows Subdivision.
- 14.) A 36" High Intensity Stop sign installed on Dunbar Drive at County Road 550 East in Dunbar Highlands Subdivision.
- 15.) A 30" High Intensity Stop sign installed on Amelia Avenue at Creasy Lane in Crosspointe Industrial Subdivision.
- 16.) A 36" High Intensity Yield sign installed on Buckingham Way at Buckingham Drive in Buckingham Subdivision, Part I.
- 17.) 36" High Intensity Yield signs installed on Buckingham Circle at Buckingham Drive in Buckingham Subdivision, Part I.
- 18.) A 36" High Intensity Yield sign installed on Nottingham Drive at Buckingham Drive in Buckingham Subdivision, Part I.
- 19.) A 36" High Intensity Yield sign installed on Norwick Drive at Buckingham Drive in Buckingham Subdivision, Part I.

- 20.) A 36" High Intensity Yield sign installed on Yarmouth Drive at Norwick Drive in Buckingham Subdivision, Part I.
- 21.) A 36" High Intensity Yield sign installed on Prion Court at Admiral's Pointe Drive in Raineybrook Subdivision, Phase II.
- 22.) A 36" High Intensity Yield sign installed on Osprey Drive East at Admiral's Pointe Drive in Raineybrook Subdivision, Phase II.
- 23.) A 30" High Intensity Stop sign installed on Botanical Lane at County Road 400 East in Garden View Subdivision.
- 24.) A 30" High Intensity Stop sign installed on Trotter Drive at South Brookfield Drive in Arlington Commons Subdivision, Phase I.
- 25.) A 36" High Intensity Yield sign installed on Atwood Drive at Trotter Drive in Arlington Commons Subdivision, Phase II.
- 26.) A 36" High Intensity Yield sign installed on Atwood Drive at Pioneer Drive in Arlington Commons Subdivision, Phase II.
- 27.) A 36" High Intensity Yield sign installed on Stanton Drive at Pioneer Drive in Arlington Commons Subdivision, Phase II.
- 28.) A 36" High Intensity Yield sign installed on Stanton Drive at Trotter Drive in Arlington Commons Subdivision, Phase II.
- 29.) A 30" High Intensity Stop sign installed on Pioneer Drive at South Brookfield Drive in Arlington Commons Subdivision, Phase I.
- 30.) A 36" High Intensity Yield sign installed on Lochan Court at Foxmoor Lane in Meadows at Northridge Subdivision.
- 31.) A 30" High Intensity Stop sign installed on Farmington Court at Flowering Crab Drive West in Farmington Subdivision, Phase IB.
- 32.) A 36" High Intensity Yield sign installed on Perishing (sic) Drive at Mar Ruth Drive in Watkins Glen Subdivision, Phase IV, Part 2.
- 33.) A 30" High Intensity Stop sign installed on Brunswick Drive at Old Romney Road in Winfield Farms Subdivision, Phase I.
- 34.) A 36" High Intensity Yield sign installed on Butterfield Court at Brunswick Drive in Winfield Farms Subdivision, Phase I.
- 35.) A 36" High Intensity Yield sign installed on Chardonnay Court at Brunswick Drive in Winfield Farms Subdivision, Phase I.
- 36.) A 36" High Intensity Yield sign installed on Kilbourne Court at Brunswick Drive in Winfield Farms Subdivision, Phase I.
- 37.) The existing Yield sign replaced with a 30" High Intensity Stop sign on Wolflake Drive at South Brookfield Drive in Brookfield Farms Phase I.
- 38.) A 30" High Intensity Stop sign installed on Old Romney Road at County Road 350 South.
- 39.) The existing Yield signs replaced with 30" High Intensity Stop signs on County Road 225 West at County Road 600 North.
- 40.) A 30" High Intensity Stop sign installed on Vicksburg Lane East at Mason--Dixon Drive in Kimberley Estates Subdivision Part 2.
- 41.) The existing Yield sign replaced with a 30" High Intensity Stop sign on Vicksburg Lane West at Mason-Dixon Drive in Kimberley Estates Subdivision Part 2.
- 42.) A 30" High Intensity Stop sign installed on McClellan Lane at Mason-Dixon Drive in Kimberley Estates Subdivision Part 2.

